


REV.	DESCRIPTION	DATE	BY	ECO
A	INITIAL RELEASE	10 SEP 2013	K. MARETT	4070
B	COMBINED S2103.01 AND PRM2103 DRAWINGS	5/11/2018	D. WILDING	4699
C	UPDATED INSTRUCTIONS FOR CLARITY	12/21/2020	D. WILDING	5073



COMPLETED
SUB-ASSEMBLY



NOTES:

1. See BOM provided by PCB for component identification. All equivalencies must be approved by PCB engineering.
2. See D0001.8362 S2103.01 ASSEMBLY & TEST INSTRUCTIONS for detailed assembly and test procedures for the preamp.
3. Completed assembly must be RoHS compliant: USE LEAD-FREE SAC305 SOLDER where applicable.

PROPRIETARY AND CONFIDENTIAL THIS DOCUMENT, SUBMITTED IN CONFIDENCE, CONTAINS PROPRIETARY INFORMATION WHICH SHALL NOT BE REPRODUCED OR TRANSFERRED TO OTHER DOCUMENTS OR DISCLOSED TO OTHERS OR USED FOR ANY OTHER PURPOSE WITHOUT THE WRITTEN PERMISSION OF PCB PIEZOTRONICS, INC.
 COPYRIGHT © PCB PIEZOTRONICS, INC. FILE NAME: PRM2103 subassy, 0.5in preamp 10-pin LEMO with calib check

AUTHOR
K. MARETT
DATE
2/22/2012


LARSON DAVIS
A PCB PIEZOTRONICS DIV.
Provo, Utah, USA (801) 375-0177

TEMPLATE: D2140-0023 [1-1]


TITLE
ASSY, 1/2" PREAMP W/
CALIB CHECK

SIZE B	NUMBER PRM2103	REV. C
SCALE 1:1	SHEET 1 OF 7	


STEP 1 - PLACE 1170.0045 10 - PIN CONNECTOR, M2103.04 INNER INSULATOR WITH INSERTED 1470.0011 POGO PIN, AND A2103.01 PCBA (BOTTOM SIDE UP) INTO THE T2103.01 SOLDERING FIXTURE.




STEP 2 - SOLDER THE POGO AND 10 PIN CONNECTOR AS SHOWN BELOW ON THE BOTTOM SIDE OF THE BOARD




STEP 3 - FLIP OVER PCBA. SOLDER POGO AND 10-PIN CONNECTOR AS SHOWN BELOW



STEP 4 - SOLDER UPPER TWO PINS TO PCBA USING 2 QTY 30 AWG WIRES AS SHOWN BELOW




STEP 5 - PLACE PCB SIDEWAYS INTO T2103.01 FIXTURE AND PLACE POGO INTO FIXTURE HOLE. SOLDER THE GROUNDING POGO WHILE IN THE FIXTURE.



STEP 6 - CLEAN THE BOARD WITH SPRAY ELECTRONICS CLEANER

STEP 7 - PERFORM THE BOARD LEVEL SIGNAL TEST PER SECTION 9.1 IN THE D0001.8362 S2103.01 ASSEMBLY & PRM2103 TEST INSTRUCTION.


STEP 8 - SLIDE THE GUARD TUBE OVER THE INNER INSULATOR WITH THE GROOVES LINED WITH THE PCBA. TUBE WILL "SNAP" INTO PLACE. DO NOT FORCE FARTHER AND DO NOT TRIM THE BOARD. SOLDER INTO PLACE.




CLEAN SOLDER FLUX OFF OF THE GUARD TUBE.

WARNING: DO NOT CLEAN WITH GUARD TUBE POINTED DOWN.


STEP 9 - REMOVE THE HUMIDITY AND TEMPERATURE SENSOR COVER AND SOLDER TO THE PCBA (U2).




STEP 10 - WRAP THE GUARD TUBE WITH MYLAR TAPE THREE TIMES WITH MYLAR TAPE THREE TIMES




STEP 12 - INSPECT THE TWO SOLDERED ON WIRES ON THE 10-PIN CONNECTOR AND VERIFY THAT THEY ARE PLACED SUFFICIENTLY ABOVE THE OTHER PADS DIRECTLY ON THE BOARD, AND HAVE NOT BEEN PUSHED DOWN (POTENTIALLY SHORTING TO THE OTHER PADS).




STEP 11 - INSERT THE OUTER INSULATOR INTO THE OUTER PREAMP TUBE. USE T2103.03 TOOL TO STRETCH OUT INSULATOR BY INSERTING TAPERED END FROM BOTTOM SIDE OF THE PREAMP AND PRESSING AGAINST INSULATOR.



STEP 13 - ASSEMBLE THE 10 PIN CONNECTOR




STEP 14 - GENTLY INSERT THE PCBA AND CONNECTOR INTO THE BOTTOM OF THE OUTER TUBE. THREAD THE 10 PIN HOUSING INTO THE TUBE. TIGHTEN WITH 10 MM WRENCH AND RUBBER COATED SLIP-JAW PLIERS.



Important: During initial insertion, the secondary pogo might catch on the outer tube threads. You should be able to thread this pogo through the threads by turning the board while inserting. Be careful to also not break the back ground contacts when inserting the board into the outer tube.

STEP 15 - INSTALL THE O-RING ON THE TOP OF THE OUTER PREAMP TUBE IN THE THREAD RELIEF LOCATION. MEASURE THE DIMENSIONS SHOWN ON EACH PREAMP.



STEP 16 - CONTINUE WITH ELECTRICAL TESTING - SECTION 9.2 IN D0001.8362 PROCEDURE.

FINAL BOXING

0680.0005
 .500-1/2 ROUND VINYL CAP BLACK
 Cut "X" into top of cap
 Cover exposed contact on preamp.


S2103.01
 1/2" PREMP 10-PIN LEMO CALIB
 CHECK
 Center preamp in foam
 groove with engraving visible.

0860.0206
 CUSTOM FOAM INSERT 426A11
 Install foam in case.


L705.07
 CALIBRATION LABEL
 Print calibration date and calibration due date on label.
 Place label on case according to LABEL PLACEMENT DETAIL.

3255.0021
 PCB INCASE BOX SN LABEL
 Using Case Label Counter label template, print
 "PRM2103" as model number and print serial
 number as it is engraved on preamp tube.
 Place on case according LABEL PLACEMENT DETAIL.

0986.0026
 BOX CLEAR HINGED 6"x4"x1.5"
 Close box after insertion of preamp and foam.



Case Assembly



Notes:

1. See BOM as provided by PCB Engineering.
2. All equivalencies must be approved by PCB Engineering.
3. All components and processes must be ROHS compliant.
4. Labels may not appear as shown.