


Internal Star Washer




1470.0013

Fully seat pogo in BNC solder cup and apply minimal solder, avoid solder incursion into pogo's open end.



m730.18 SPACER



0746.0081 CAP CER 11pF COG

P730.05

1132.0042 (Large dia. to PCB)



m730.17 OVERTUBE

3255.0008 LABEL, PRINT "ADP106"

# LARSON-DAVIS

## ADP106 Input Adapter Assembly Drawing

Created: 09Jul2018	By: Alan Rasmussen	Rev.
Revised: 09Jul2018	By: Alan Rasmussen	A