

1. RTV material is identified by:
  - a. A sticker on the inspection lot print out
  - b. The SAP location is 1081
  - c. The SAP usage decision
  - d. NC SharePoint entry
  - e. **All of the above**
  
2. For large NC materials, Material Handling physically moves the material to 1081 and delivers the inspection lot and the pink "RTV Move Request" form to shipping.
  - a. **True**
  - b. False
  
3. Upon return from the vendor for replacement, material is:
  - a. Sent directly to stock
  - b. **Verified by Quality Inspection**
  - c. Assigned a new Inspection lot
  - d. Follows the nonconforming process
  
4. The Purchasing MRP Controller is notified of an RTV by the Quality Technician.
  - a. True
  - b. **False**
  
5. For small materials, the Quality Technician completes all the following tasks except:
  - a. Marks material RTV
  - b. Moves material physically and in SAP to 1081
  - c. **Initiates QN**
  - d. Creates a new entry in the NC SharePoint
  
6. Shipping completes the following tasks: completes the SAP movement to 1081 for large materials, locates the material when the delivery note is printed, packages the material for shipment, completes the delivery note in SAP, and updates the log sheet in 1081 for materials added to the list by the Quality Technician.
  - a. **True**
  - b. False